12/1/80

BILL -

I WISH I COULD SAY IT WORKED LIKE A CHAMP ALL EVENING. IT DID FOR ABOUT AN HOUR — THEN LOCKED UP DURING PLAYBACK. NO OUTWARD SIGNS - JUST WOULD NOT START OR ABORT. "16001" CAUSED TAPE 1 TO MOVE ABOUT 2" OR SO EITHER TAPE DECK. RELOAD SYSTEMS. "16001" GOT IT BACK - ONLY TO DO THE SAME THING WITHIN SECONDS.

IT'S PLAYED THE SAME GAME WITH VARIATIONS ALL EVENING

VARIATIONS: NO TAPE MOVEMENT ON "16001".

RELOAD SYSTEMS. '16001' - ADVANCE TAPE AN INCH OR TWO.

REENTER '16001' - " " " " "

BLANKS FIRST FOUR LINES OF ALPHANUMERIC PRIOR TO CRASHING ... OR DOESN'T.

SHUT OFF COMPUTER AND RESTART AND MEM LOC 11* MAY OR MAY NOT BE BOMBED.

ALL FAILURES SO FAR ARE ON LEFTHAND PEC DECK — POSSIBLY ONLY BECAUSE I CAN'T KEEP IT UP LONG ENOUGH TO HAVE A FAILURE ON THE RIGHTHAND ONE...

THE AIRCONDITIONER SEEMS TO BE FROZEN SOLID, BUT TEMPERATURES ONLY ABOUT 75°F. VOLTAGES READ 14.93 - 15.33.

OR, TO PUT IT IN A MYTHOLOGICAL ALLEGORICAL WAY...

WE GOT AT LEAST ONE MORE BAD IC IN THERE SOMEWHERE....